

Coos Bay Harbor Safety Plan
Appendix C

Appendix C - ATON

ATON Name/Lat/Long	Proposal	Status	Conclusion	Date
Guano Rock: Buoy R 4 has washed downstream from the rock and affects outbound traffic mostly.	Relocate it to clearly mark the location of Guano Rock	Closed	US Coast Guard is not planning on changing it.	Aug 2017